

## **Addendum for SY-7IWB and 7IWM/L Motherboards**

### **Following is a list of known issues for the 7IWB and 7IWM/L Motherboards**

1. When using the Smartlink MR (Modem Riser) card, sometimes the system will reboot or hang when it is restarting.
  - *This is due to an audio codec driver bug. To solve this issue, make sure that 'Modem Ring On' option in the BIOS is set to disabled; this will ensure the system shuts down properly.*
2. When resuming back from standby or suspend with the Smartlink MR card plugged in, the AC97 codec will be not working properly.
  - *This issue is known and currently under investigation.*
3. Once the Logitech USB joystick "Wingman Force" has been installed, Windows can not shutdown.
  - *This is a BIOS issue. It will be fixed in a future revision of the BIOS.*
4. Under Win98, the recording function is not working properly.
  - *This is an Audio codec driver issue. It will be fixed in a future version of the driver.*

The latest driver and utilities will be posted on Soyo's web site <http://www.soyo.com.tw> periodically.

Please go to Soyo web site to check for new driver and BIOS releases regularly.

**990902**