Please note that when you installed the VIA service pack driver and then reboot your system, the file Digital.inf on AGP VxD Disk is missing. Please follow the instruction below to finish the installation process.

1. You will be prompt to insert the "AGP VxD Disk"(Figure 1-1). **Click "OK".**

Figure 1-1

2. After clicking "**OK**", you will be prompt that the file Digital.inf on AGP VxD Disk can not be found (See figure 1-2 below). Click on the **"Skip File"** to finish Installation.


Figure 1-2

Note: The Digital.inf file was not included in this service pack was due to the fact that Microsoft Digital Logo Certificate is not yet issue to VIA prior to the release of this mainboard.