


Addendum (25-10865-30)

To : Users of Manuals for VA-503+ (part no: 25-10865-21 and 25-10865-01)

Some information in this manual were corrected. They were 3 items listed below:

1. Page 8, 15, 18-

The jumpers' location of SDRAM1, 2, 3 and FREQ1, 2, 3 should be :



2. Page 23, 25 (25-10865-01 only)

The photo of EICA should be exchanged with that of CHAS_FAN.

3. Page 28

the ATX power supply connector is manufacturing optional.