

Rework Instruction

1. At location RN73 (8P4R, 8pin with 4 elements), please replace the resistor net from 2.2K (222) to 4.7K (472) .
2. Add one piece of 104 (0.1U) monolithic capacitor across the lower end of R342 and the ground as shown in picture.

