



Product: SiS USB2 Driver

Date: 01/24/2003

Document Type : Release Note

Driver. No.: 1.02

SiS USB2 Driver [V1.02]

1. In USB logo driver v1.02, no USB driver update from driver USB driver v1.01.

Modification

1. Remove WindowsXP USB2 driver from the package. The SiS USB2 Driver V1.02 and later version can only support Windows2000. For using WindowsXP, SiS recommends users to use WindowsXP SP1 inbox USB 2.0 driver.